Oil Field Environmental Incident Summary

Responsible Party: Wind River Trucking

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: FRISCO 1-31H

Field Name: GLASS BLUFF Well File #: 22905

Date Incident:6/4/2015Time Incident:17:00Facility ID Number:County:MCKENZIETwp:152Rng:102Sec:31Qtr:

Location Description:

Submitted By: Justin Collins Received By:

Contact Person: Justin Rose

310 Airport Road Suite 100 Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 30 Barrels 30 Barrels 30 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/3/2016 Clean Up Concluded: 6/6/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Sucked up standing water. Remove contaminated material.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 6/5/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.